



REQUEST FOR QUOTATIONS FOR SERVICES FOR MSUKALIGWA LOCAL MUNICIPALITY

Procurement Less than R 200 000.00 (Including Vat)

Publication on the Msukaligwa Local Municipality Notice Board/s & Website

Msukaligwa Local Municipality invites suitable service providers to submit quotation on the goods and/ or services listed hereunder. Please furnish all information as requested and return your quotation document on the date stipulated.

ADVERTISEMENT DATE	04/09/2017													
DEPARTMENT	Finance													
DESCRIPTION SERVICES REQUIRED	<p style="text-align: center;">MAJOR SERVICE AND PUMP OPERATION CERTIFICATION OF A 1992 GMC TOP KICK FIRE ENGINE</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr><td>Travelling Km Costs – from service providers business to Ermelo</td></tr> <tr><td>Travelling Time</td></tr> <tr><td>Service Engine</td></tr> <tr><td>Replace P55-7440 Fuel Filter</td></tr> <tr><td>P55-4004 Lube Spin - On</td></tr> <tr><td>P55-6005 Hydraulic Filter Spin On</td></tr> <tr><td>Replace P52-7484 Air Filter</td></tr> <tr><td>Engine Oil :- 15W40</td></tr> <tr><td>Anti-freez</td></tr> <tr><td>Replace Fan Belt</td></tr> <tr><td>Replace Altinator Belt</td></tr> <tr><td>Service Pump according to manufactures specifications</td></tr> <tr><td>Pump drafting certification according to manufactures specification</td></tr> </table>	Travelling Km Costs – from service providers business to Ermelo	Travelling Time	Service Engine	Replace P55-7440 Fuel Filter	P55-4004 Lube Spin - On	P55-6005 Hydraulic Filter Spin On	Replace P52-7484 Air Filter	Engine Oil :- 15W40	Anti-freez	Replace Fan Belt	Replace Altinator Belt	Service Pump according to manufactures specifications	Pump drafting certification according to manufactures specification
Travelling Km Costs – from service providers business to Ermelo														
Travelling Time														
Service Engine														
Replace P55-7440 Fuel Filter														
P55-4004 Lube Spin - On														
P55-6005 Hydraulic Filter Spin On														
Replace P52-7484 Air Filter														
Engine Oil :- 15W40														
Anti-freez														
Replace Fan Belt														
Replace Altinator Belt														
Service Pump according to manufactures specifications														
Pump drafting certification according to manufactures specification														

	80W90 - Gear Oil
	Grease all relevant joints
	Repair Flood Lights
	Replace flood lamps with Utility Bar 8" - Single Flood 12V - 56V (x 2)
	Female Duetch Connector
	Male Deutch Connector
	Service Brakes Remove Front Brakes and replace with new
	Service Brakes Remove Rear Brakes and replace with new
	Clean & Adjust Brakes Front
	Clean & Adjust Rear Brakes
	Repair Park brake
	Repair Park brake Valve
	Parts - Workshop Team
	Supply two Wheel Chocks
	Service electrical motor system high pressure hose reel
	Replace defective lamps of main warning light - Federal signal (Aerodynamic) light bar
	Service front bumper fitted Ramsey 8000 electric winch
	Replace 2 x 65mm x 30m rubber fire hoses
	Replace 4 x 38mm x 30m rubber fire hoses
	Additional ad on cost envisage by bidder not covered under the above items
	I.
QUANTITY	1
QUOTATION NUMBER	35
CLOSING DATE & TIME:	12/09/2017 at 11am
ENQUIRIES:	Mr.D.J.JOHNSTONE Tel: 017 801 3400

Price should be VAT Inclusive. A valid original Tax Clearance Certificate, certified identification copy or company registration certificate and current municipal account (not older than 60 days) or lease agreement must be attached and the declaration of interest form must be filled in, BBBEE certificate must be attached, all suppliers must register in central supplier database (CSD).

Documents are available in SCM unit and be delivered to the following address Cnr Church & Taute Street Ermelo 2350. Failure to attach the requested documents or incomplete quotation document will result in a bid being non-responsive.

Quotation must have a vat registration number, description, company address, contact details, quotation date, and name and address of the company you quote for.

Yours faithfully

A handwritten signature in black ink, appearing to read 'MMP Matsheka', is written over a horizontal line.

MMP MATSHEKA
CFO